Portable Reference Electrodes Copper-Copper/ Sulfate

MODELS: 2-A PENCIL CELL 3-A FOR CONCRETE 6-A, 8-A FLAT TIPS 6-B, 8-B POINTED TIPS

COPPER SULFATE

Features:

- Long lasting tips
- Strong body for outdoor use
- High purity copper
- High purity coppersulfate
- Optional Clear View tube
- Temperature sensor



Info@tinker-rasor.com | tinker-rasor.com

Tinker & Rasor quality is found in our products, our people and our customer service.

INKER & RASOR

PRODUCT DATA SHEET | MODELS 2-A, 3-A, 6-A, 6-B, 8-A AND 8-B

FEATURES:

- Flat or Pointed Tips
- Tip grooves provide greater surface area
- Tips pre-saturated with copper-sulfate
- Knurled nut on 1/4" 20 (except 2-A) threaded rod for easy lead connection (fork, ring, etc)
- Model 2-A, #6 knurled nut on 10-32 threaded copper rod.
- Charged with copper-sulfate
- Multiple Diameters and Lengths available

CONSTRUCTION:

- New, tougher body
- Optional Clear View Tube
- Stronger, longer lasting tips
- O-ring seals

APPLICATIONS:

- Pipe to Soil potentials
- Close Interval Surveys
- Structure to Cell
- Lab use

RECOMMENDATIONS:

Use with most CP Voltmeters Half cell models 3, 6 & 8 screw into back of T&R CPV-2 and CPV-4 CP Voltmeters

SPECIFICATIONS:

High purity copper rod High purity copper-sulfate crystals

DIMENSIONS:

2-A: 3/8" x 5-3/4" 3-A: 3" x 5" 6-A: 1-1/4" x 6" 6-B: 1-1/4" x 7" 8-A: 1-1/4" x 8" 8-B: 1-1/4" x 9"

DELIVERY:Immediately from STOCK
F.O.B. New Braunfels, TX USASERVICE:24-hour Turn-AroundTERMS:Net 30 Days, on approval of creditWARRANTY:90 Days, parts and labor



HALF CELLS, CP VOLTMETERS AND EXTENSION HANDLES

AVAILABLE FROM STOCK

tinker-rasor.com